



DCS QuickSticks

Clay Dispersant for Bit Balling and Torque Reduction

Description

QuickSticks are wrapped in quick dissolving tubes that can be put into the drill pipe and pumped downhole to clear clay stuck to the bit and drill pipe. Using QuickSticks will reduce torque and improve the rate of penetration.

Characteristics

- When added directly down the drill pipe to clear bit balling, QuickSticks will breakdown the clay and sweep it from the bit and drill pipe
- QuickSticks will also treat the clay downhole by weakening the reactivity that causes it to stick and swell
- Torque is reduced by clearing the clay from the BHA
- The wrapping will self-dissolve when exposed to water and pumped downhole
- Dimensions: 1 5/8" X 12"

Mixing Dosage Rates

- To clean clay off the BHA and pipe: add 1-2 QuickSticks down the drill pipe on connection. Pump as normal while drilling ahead.

Packaging

DCS QuickSticks are available in 5-gallon pails with 22 wrapped sticks per pail